

## TABLES

1.1	Powders handled in TA-3-141 in decreasing order of usage and potential hazard . . . .	1-6
1.2	Levels of concern for contaminants in TA-3-141 . . . . .	1-15
2.1	Number and locations for metal wipe samples . . . . .	2-
2.2	Samples with major interference problems . . . . .	2-5
2.3	Summary of quality control (duplicate) samples for wipes . . . . .	2-7
2.4	Bulk dust samples with major interferences . . . . .	2-
3.1	Wipe samples collected from the exhaust ventilation system in beryllium process areas (new FE-1) . . . . .	3-4
3.2	Wipe samples collected from the exhaust ventilation systems in radiological/ process areas . . . . .	3-6
3.3	Wipe samples collected from the supply ventilation system in the beryllium process area . . . . .	3-9
3.4	Summary of wipe samples collected in supply ventilation systems serving radiological/process areas . . . . .	3-10
3.5	Summary of wipe samples collected in supply ventilation systems serving office areas . . . . .	3-12
3.6	Summary of wipe samples collected from walls in beryllium process areas . . . . .	3-14
3.7	Summary of wipe samples collected from walls in radiological/process areas . . . . .	3-15
3.8	Summary of wipe samples collected from walls in office areas. . . . .	3-16
3.9	Summary of wipe samples collected from rotating equipment in beryllium process areas . . . . .	3-18
3.10	Summary of wipe samples collected from rotating equipment in radiological/ process areas . . . . .	3-19
3.11	Summary of horizontal wipe samples collected in beryllium process areas . . . . .	3-21
3.12	Summary of horizontal wipe samples collected in radiological/process area - < 6 ft . .	3-22
3.13	Summary of horizontal wipe samples collected in radiological/process area - > 6 ft . .	3-23
3.14	Summary of horizontal wipe samples in radiological/process areas - equipment . . . .	3-24
3.15	Summary of horizontal wipe samples collected in office areas - < 6 ft . . . . .	3-26
3.16	Summary of horizontal wipe samples collected in office areas - > 6 ft . . . . .	3-27
3.17	Results of oil stains for PCBs . . . . .	3-28
3.18	Bulk dust sample results . . . . .	3-30
3.19	Roof bulk sample results . . . . .	3-34
3.20	Paint sample results . . . . .	3-37
3.21	LANL TA-3-141 physical hazards summary . . . . .	3-39
3.22	Confined spaces for TA-3-141 and surrounding locations . . . . .	3-41
3.23	Summary of beryllium air concentrations in beryllium process areas . . . . .	3-42
3.24	Summary of beryllium surface concentrations in beryllium process areas . . . . .	3-43
3.25	Summary of lead concentrations in beryllium process areas . . . . .	3-44
3.26	Radiological survey summary . . . . .	3-45
4.1	LANL TA-3-141 renovation—suggested personal protective equipment . . . . .	4-15